




Custom Dynamics® Tech Bulletin
Water Intrusion HD Auxiliary Lighting Kits
(68000043, 8000042, 67800366A, 69228-04, 69230-04, 69818-06)

We have seen several touring models where the turn signals mount under the passing lamp bracket, have excessive water damage inside the turn signal housing. This is not from adding aftermarket lighting as it is happening with bikes that have OEM turn signal lenses and bulbs installed.



Water is entering the turn signal housing from one of two places. Water can enter through the Allen head mounting bolt (See Arrow A). Water can also enter through the top and bottom of the turn signal mount (See Arrow B).

Preventive measures need to be taken to seal the areas to prevent water from entering into the turn signal housing and causing excessive water damage to the inside of the turn signal housing.

Questions? Call us at: 1 (800) 382-1388 M-TH 8:30AM-

Here is an example of a bike and what happens if this issue is not addressed.

