


**Confirm Continuity With a Multi-Meter or Test Light:**

|           |           |
|-----------|-----------|
| A1 to E16 | A6 to B8  |
| A2 to B7  | A6 to C10 |
| A3 to D11 | A6 to D13 |
| A3 to E17 | A6 to E14 |
| A4 to D12 |           |
| A4 to E15 |           |
| A5 to C9  |           |

|   |              |   |
|---|--------------|---|
| Date: 03/23/16  | Page: 1 of 1 | Technical   |
| <b>TL-CKTBD Testing Procedure</b>   |              |   |
|  |              | Custom Dynamics, LLC<br>15 Cypress Drive<br>Youngsville, NC 27596 USA<br>Phone: (800) 382-1388<br>Fax: (919)882-9611<br>Email: sales@customdynamics.com |